

Electrical Power

Basic Electrical Testers

Cable Testers

Clamp Meters

Digital Multimeters

Graphical Multimeters

Power Quality Tools

Power Glossary

Process Products

Thermometers

Application Notes

Downloads

Fluke 30/32 Clamp Meters Specifications

[[Product Home](#)] [[Features](#)] [[Specifications](#)] [[Models, Options & Accessories](#)]

- [General Specifications](#)
- [30 Clamp Meter](#)
- [32 Clamp Meter](#)

General Specifications

Operating Temperature	10oC to +50oC (14oF to 122oF)
Battery Life	200 hours typical (Alkaline for Model 32, Carbon-zinc for Model 30). Automatic Low-battery indicator
Size	213 mm L x 93 mm W x 45 mm D (8.4" L x 3.75" W x 1.77" D)
Weight:	0.45 kg (1 lb.)
Warranty	One Year

30 Clamp Meter

AC Current	Range: 600A, 400A, 200A Resolution: 1A, 1A, 0.1A Accuracy: N/A, $\pm(1.3\%+3)$, 0-100A: $\pm(1.8\%+8)$, 100-200A: $\pm(1.4\%+0)$
AC Volts 50/60 Hz	Range: 200V, 600V Resolution: 0.1V, 1.0V Accuracy: $\pm(1.2\%+3)$
Resistance	Range: 200 Ω Resolution: 0.1 Ω Accuracy: $\pm(1.5\%+2)$
Crest Factor	Range: 400A, 200 Resolution: Accuracy: N/A

32 Clamp Meter

AC Current	Range: 600A, 400A, 200A Resolution: 1A, 1A, 0.1A Accuracy: $\pm(2.5\%+3)$, $\pm(1.3\%+3)$, 0-100A: $\pm(1.8\%+8)$, 100-200A: $\pm(1.4\%+0)$
AC Volts 50/60 Hz	Range: 200V, 600V Resolution: 0.1V, 1.0V Accuracy: $\pm(1.2\%+3)$
Resistance	Range: 200 Ω Resolution: 0.1 Ω Accuracy: $\pm(1.5\%+2)$
Crest Factor	Range: 400A, 200 Resolution: Accuracy: N/A

© 1995 - 1999 Fluke Corporation

[Privacy Statement](#)