



! " # \$ % & ' () * + \$! , * , - .

&'() ! *(+,-./'01!

! TP7-C THERMOMETERS !

TP7C-012AW-MM	TP7-C Thermometer, 12ft (4m) cable, Asphalt Weight Probe, Brass Markers at 1 meter intervals, ATEX/ IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-012EW-NM	TP7-C Thermometer, 12ft (4m) cable, Extra Weight Probe, No Brass Markers, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-012EW-SM	TP7-C Thermometer, 12ft (4m) cable, Extra Weight Probe, Brass Markers at 5ft (1.5m) intervals, ATEX/ IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-012RC-MM	TP7-C Thermometer, 12ft (4m) cable, Railcar (No Weight) Probe, Brass Markers at 1 meter intervals, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-012RC-NM	TP7-C Thermometer, 12ft (4m) cable, Railcar (No Weight) Probe, No Brass Markers, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-012RC-SM	TP7-C Thermometer, 12ft (4m) cable, Railcar (No Weight) Probe, Brass Markers at 5ft (1.5m) intervals, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-012SW-MM	TP7-C Thermometer, 12ft (4m) cable, Standard Weight Probe, Brass Markers at 1 meter intervals, ATEX/ IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-012SW-NM	TP7-C Thermometer, 12ft (4m) cable, Standard Weight Probe, No Brass Markers, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-012SW-SM	TP7-C Thermometer, 12ft (4m) cable, Standard Weight Probe, Brass Markers at 5ft (1.5m) intervals, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-020EW-MM	TP7-C Thermometer, 20ft (6m) cable, Extra Weight Probe, Brass Markers at 1 meter intervals, ATEX/ IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-020EW-NM	TP7-C Thermometer, 20ft (6m) cable, Extra Weight Probe, No Brass Markers, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-020RC-NM	TP7-C Thermometer, 20ft (6m) cable, Railcar (No Weight) Probe, No Brass Markers, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-020RC-SM	TP7-C Thermometer, 20ft (6m) cable, Railcar (No Weight) Probe, Brass Markers at 5ft (1.5m) intervals, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-020SW-NM	TP7-C Thermometer, 20ft (6m) cable, Standard Weight Probe, No Brass Markers, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-020SW-SM	TP7-C Thermometer, 20ft (6m) cable, Standard Weight Probe, Brass Markers at 5ft (1.5m) intervals, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-025AW-SM	TP7-C Thermometer, 25ft (7.5m) cable, Asphalt Weight Probe, Brass Markers at 5ft (1.5m) intervals, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-025EW-MM	TP7-C Thermometer, 25ft (7.5m) cable, Extra Weight Probe, Brass Markers at intervals, ATEX/ IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-025EW-NM	TP7-C Thermometer, 25ft (7.5m) cable, Extra Weight Probe, No Brass Markers, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-025EW-SM	TP7-C Thermometer, 25ft (7.5m) cable, Extra Weight Probe, Brass Markers at 5ft (1.5m) intervals, ATEX/ IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-025RC-MM	TP7-C Thermometer, 25ft (7.5m) cable, Railcar (No Weight) Probe, Brass Markers at 1 meter intervals, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-025RC-NM	TP7-C Thermometer, 25ft (7.5m) cable, Railcar (No Weight) Probe, No Brass Markers, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-025SW-NM	TP7-C Thermometer, 25ft (7.5m) cable, Standard Weight Probe, No Brass Markers, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C
TP7C-025SW-SM	TP7-C Thermometer, 25ft (7.5m) cable, Standard Weight Probe, Brass Markers at 5ft (1.5m) intervals, ATEX/IECEx Certification (Ex ib [ia] IIB T4), Ambient temperature range -20°C to +40°C