

# Supplement

Title:	700PTP-1 I.S.	Supplement Issue:	<b>2</b>
Part Number:	2811824	Issue Date:	3/11
Print Date:	April 2007	Page Count:	1
Revision/Date:			

---

---

This supplement contains information necessary to ensure the accuracy of the above Instruction Sheet.

## Change #1

Replace the ***Replacement Parts*** section with the following:

Hose Assembly, Fluke PN 2815723

Rebuild Kit, Fluke PN 3093412

Bleed Valve Assembly (Needle), Fluke PN 2844329

Handle Assembly Rebuild Kit, Fluke PN 2844352

## Change #2, 57806

Under ***Introduction***,

Change: Vacuum to -0.96 bar (-13.9 psi)

To: Vacuum to -0.87 bar (-12.7 psi)