TH8P2



Phone: 1-800-757-3747 | Fax: 1-800-676-0498 | Email: dicksoncsr@dicksondata.com | For calls outside the US please call: 1-630-543-3747

8" (203mm) Temperature & Humidity Chart Recorder





► Visit us at Transcat.com!

35 Vantage Point Drive // Rochester, NY 14624 // Call 1.800.800.5001

Specifications

Ambient Operating RH Conditions: 0-95% RH non-condensing **Ambient Operating Temperature Conditions**: 32 to 120F (0 to 50C)

Approvals: CE

Battery Backup: Four AA Batteries. Powers unit for up to 3 Days.

Battery Life (Avg): 76 Hours (Back-up Only)
Calibration Options: N100, N300, N400
Channels: CH1: Temperature, CH2: Humidity
Chart Rotation Speed: 24 Hour, 7 Day or 31 Day

Dew Point Accuracy: +/-3.6F from 30 to 95% RH (Calculated) (+/-2C from 30 to 95% RH (Calculated))

Dew Point Range: 32 to 122F (0 to 50C)

Dimensions: 3.1 x 9.2 x 9.2in **Display Dimensions Height:** 1.375 **Display Dimensions Width:** 2.0

Display Resolution: 0.1 **Display Type:** LCD

Enclosure: Rugged Black ABS Case, Polycarbonate Door, Aluminum Dial **Humidity Accuracy:** +/-2% RH from 0 to 60%; +/-3% RH from 60 to 95%

Humidity Range: 0-95% RH non-condensing Humidity Sensor Type: Field Replaceable

IP Rating: 20

Included Accessories: AC Adapter, Red and Blue Pen, Four AA Batteries and Quick Start Guide. *Charts sold

separately.

Keypad Functions: Power On/Off, Pen Home

Mounting Options: Free Standing or Wall Mount (With Keyhole)

Power Cord: 6 ft

Power Source: 120 to 240 VAC, 12 VDC (INTL fittings available); AC Adapter

Power Status Indicator: LED Indicator

Response Time: 5 Minutes to 63% of Full Scale

Temperature Accuracy: +/-1.8F from 32 to 120F (+/-1C from 0 to 50C) **Temperature Range:** 32 to 120F (0 to 50C); 40 to 110F (5 to 40C)

Unit Weight: 9 lbs

Units/Pkg: 1

Warranty: 12-Month Limited



TH8P2

Phone: 1-800-757-3747 | Fax: 1-800-676-0498 | Email: dicksoncsr@dicksondata.com | For calls outside the US please call: 1-630-543-3747

Accessories TH8P2



Universal Plug Kit for AC Adapter Set of Three International Power Plugs for AC Adapter



AC Adapter AC Adapter

Calibrations

N100 1-Point NIST Traceable Calibration **N300** 3-Point NIST Traceable Calibration

N400 3-Point Ultima NIST A2LA Accredited Calibration



35 Vantage Point Drive // Rochester, NY 14624 // Call 1.800.800.5001