Manual Supplement

Manual Title: 71X Series Calibration Supplement Issue: 2
Part Number: 686540 Issue Date: 10/12
Print Date: January 1998 Page Count: 1

Revision/Date: 11, 3/12

This supplement contains information necessary to ensure the accuracy of the above manual.



71X Series Calibration Manual Supplement

Change #1

On page 49, under *mA Loop Power Verification*, replace step 2 with:

2. Apply 1.2 k Ω to the mA jacks from the decade box or other resistor source. The display must read >19 mA but <OL.

On page 54, under mA Loop Power Verification (718 Only), replace step 2 with:

2. Apply 1.2 k Ω to the mA jacks from the decade box or other resistor source. The display must read >19 mA but <OL.

Change #2

On page 86, Table 71,

Change:

To:

MP6 30G, 100G, 300G Pump Assembly 2558508 718 1

MP6	Fluke-718, 30G/100G, Pump with clean out	2558508	718	1
MP6	Fluke-718, 300G, Pump with clean out	2632057	718	1

10/12